


# Parallel Groove Clamp



Parallel groove connector is used for connecting or branching overhead conductors.Extruded create a high strength clamp.slotted holes allow adjusting for varying conductors on each side. its type test is accordance with IEC61238-1.Shape Body made from extruded copper or brass and bolt and spring wwasher are made of steel with hot dip galvanized plating.

TABLE

| Conductor Size mm <sup>2</sup> | Bolt     | CAT NO.   |
|--------------------------------|----------|-----------|
| 6-50mm <sup>2</sup>            | 2xM8x45  | MCBPGC-6  |
| 10-95mm <sup>2</sup>           | 3xM8x50  | MCBPGC-10 |
| 25-18mm <sup>2</sup>           | 3xM10x60 | MCBPGC-25 |
| 35-24mm <sup>2</sup>           | 3xM10x70 | MCBPGC-35 |