

Plate Type Test Clamp



Plate type test clamp are used as T Joint or straight through joints of tapes. It is also used for testing points for the network by disconnecting the joints. These also used for heavy duty tape up to 50x6 tape.

TABLE

Tape Size	CAT NO.
25x3	MCPTTC-25